GL: Emergency Relief – SHOPP Emergency Response Program (TIP ID – VAR170008)

Last updated with TIP Revision 2021-25

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
	MRN			Near Sausalito, at 0.1 mile south of Alexander Avenue.	1492J			19/20	\$3,559	\$0	\$0	\$0	\$0	\$837	\$850	\$100	\$850	\$13	\$909	\$3,559
				Restore damaged drainage systems.																
04	SM	280		In San Bruno, from Jenevein Avenue to 0.1 mile south	1499H	4J080	201.131	19/20	\$2,769	\$0	\$0	\$0	\$0	\$390	\$650	\$78	\$390	\$168	\$1,093	\$2,769
				of San Bruno Avenue. Reconstruct failed concrete																
				ditch and place Rock Slope Protection (RSP) at slope																
				washouts as storm damage permanent restoration.		<u> </u>	ime Extensi	on Total	¢6 229	\$0	\$0	\$0	\$0	\$1,227	\$1,500	\$178	\$1,240	\$181	\$2,002	\$6,328
04	ALA	880		In Hayward, at Industrial Parkwal Overcrossing No.33-	28040	1W210		20/21	\$0,320	\$2,800	\$0	\$0	\$0	\$0	\$1,500	\$178	\$800	\$101	\$2,002	\$2,800
04		000		0398. Repair bridge by replacing exterior girder,	20041	100210	201.130	20/21	ΨΟ	Ψ2,000	ΨΟ	ΨΟ	ΨΟ	ΨΟ	ΨΟ	ΨΟ	ΨΟΟΟ	ΨΟ	Ψ2,000	Ψ2,000
				adjoining deck, and barrier rail, and install advanced																
				warning signs.																
04	ALA	580		In Oakland, at Harrison Street Undercrossing No. 33-	2906M	1W540	201.130	20/21	\$0	\$1,190	\$0	\$0	\$0	\$0	\$0	\$0	\$270	\$20	\$900	\$1,190
				0289S. Construct wrought iron fencing with secured																
				access gates.																
04	ALA	880		In Oakland, at 16th Avenue Overcrossing No. 33-0137.	2907F	1W420	201.130	20/21	\$0	\$565	\$0	\$0	\$0	\$0	\$0	\$0	\$155	\$0	\$410	\$565
				Repair spalled surfaces on the soffit, secure soffit																
04	ALA	80	5.7/5.8	access, and clear out the burned material. In Berkeley, at University Avenue; also at West	2908N	1W990	201.130	20/21	\$0	\$3,600	\$0	\$0	\$0	\$0	\$0	\$50	\$950	\$50	\$2,550	\$3,600
04	ALA	00	5.7/5.6	Frontage Road onramp and offramp (PM 4.6).	2900IN	100990	201.130	20/21	φυ	φ3,000	φυ	φυ	φυ	φυ	ΦU	\$50	φ950	φου	φ2,550	φ3,000
				Construct wrought iron fencing with secured access																
				gates.																
04	ALA	880	34.2/34.6	In Oakland, along Wood Street between 14th Street	2908G	2W340	201.130	20/21	\$0	\$3,869	\$0	\$0	\$0	\$0	\$0	\$50	\$1,150	\$50	\$2,619	\$3,869
				and West Grand Avenue. Clear the area of debris and																·
				hazardous material, remove abandoned vehicles,																
				restore drainage, regrade, and construct fencing with																
				secured access gates.																
04	CC	4		In Pittsburg, at 0.4 mile east of Harbor Street. Replace	2909C	2W670	201.130	20/21	\$0	\$1,350	\$0	\$0	\$0	\$0	\$0	\$20	\$400	\$0	\$930	\$1,350
				damaged culverts, backfill eroded areas, replace																
04	СС	24	6.6/7.4	irrigation system, and install erosion control. In Lafayette, on westbound Route 24, from 1.1 miles	2007	0W610	201.130	20/21	\$0	\$1,260	\$0	\$0	\$0	\$0	\$0	\$20	\$280	\$20	\$940	\$1,260
04	CC	24	0.0/7.4	west to 0.3 mile west of Pleasant Hill Road	290711		201.130	20/21	φυ	φ1,200	φυ	φυ	φυ	φυ	φυ	φ20	φ200	φΖΟ	φ940	φ1,200
				Undercrossing. Repair settlement by injecting																
				polyurthane and grout in voids, replace culverts, and																
				repair pavement.																
04	MRN	1		Near Stinson Beach, from 1.5 miles south to 1.2 miles	2032Q	0AA48	201.131	20/21	\$311	\$1,499	\$0	\$0	\$0	\$0	\$227	\$84	\$336	\$31	\$1,132	\$1,810
				south of Panoramic Highway North. Four-year																
				mitigation plant establishment and monitoring for																
0.4	MON	101	0.5/4.0	emergency projects EA 4K240 and EA 4S220.	00071	414/500	004.400	00/04	40	# 4.040	40	40	00	40	40	00	#200	40	#700	04.040
04	MRN	101	3.5/4.8	Near Mill Valley, on northbound Route 101 at	29073	1W580	201.130	20/21	\$0	\$1,040	\$0	\$0	\$0	\$0	\$0	\$0	\$260	\$0	\$780	\$1,040
				Richardson Bay Bridge and Separation No. 27-0010. Repair expansion joints.																
04	MRN	1		Near Five Brooks, at Giacomini Creek Bridge No. 27-	2032F	0AA44	201.131	20/21	\$453	\$1,513	\$0	\$0	\$0	\$0	\$400	\$53	\$650	\$15	\$848	\$1,966
		•		0122. Four-year mitigation plant establishment for	ZOOZZ	0,011	2011101	20/21	Ψίου	Ψ1,010	ΨΟ	ΨΟ	Ψ	Ψΰ	Ψίου	ΨΟΟ	φοσσ	Ψισ	ΨΟΙΟ	Ψ1,000
				emergency project EA 4K850.																
04	NAP	29	42.1/48.6	Near Calistoga, from 2.6 miles north of Tubbs Lane to	0379T	2W760	201.130	20/21	\$0	\$6,050	\$0	\$0	\$0	\$0	\$0	\$50	\$1,500	\$0	\$4,500	\$6,050
				Lake County line. Repair damaged roadway by grinding																
				and overlaying with rubberized asphalt.																
04	NAP	29	33.5/48.6	In and near Calistoga, from Lakemead Lane to Lake	2907B	1W630	201.130	20/21	\$0	\$5,320	\$0	\$0	\$0	\$0	\$0	\$20	\$1,200	\$100	\$4,000	\$5,320
				County line; also in and near Santa Rosa in Sonoma																
				County on Route 12, from 0.1 mile east of Acacia Lane																
				to Hoff Road (PM 19.3/25.8). Repair or replace guardrails, ditches, signs, fencing, drainage and																
				electrical facilities, remove debris and hazardous trees,																
				repair pavement, and install erosion control in fire																
				damaged areas.																

July 27, 2022 1 of 6

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
04	NAP			In Napa and Solano Counties on Routes 121 and 128	2905D	1W480		20/21	\$0	\$10,420	\$0	\$0	\$0	\$0	\$0	\$0	\$2,400	\$20	\$8,000	\$10,420
				at various locations. Repair culverts, retaining walls,																
				and pavement, remove hazardous trees, replace																
				guardrails, and install erosion control in fire damaged																
				areas.																
04	SCL	35		Near Los Gatos, at 1.8 miles north of Black Road.	2035F	0W170	201.130	20/21	\$0	\$1,700	\$0	\$0	\$0	\$0	\$0	\$0	\$400	\$0	\$1,300	\$1,700
0.4	001	400		Stabilize slope and improve drainage systems.	00001	4)4/000	004.400	00/04	00	00.040	40	00	00	40	00	000	#4.050	# 400	0.4.500	#0.040
04	SCL	130		Near San Jose, from Quimby Road to Observatory	2906N	1W620	201.130	20/21	\$0	\$6,010	\$0	\$0	\$0	\$0	\$0	\$60	\$1,350	\$100	\$4,500	\$6,010
				Peak Road. Repair damaged culverts and pavement,																
				replace signs and delineators, and install erosion control in fire damaged areas.																
04	SCI	130		Near San Jose, from 0.8 mile west of Smith Creek	29060	1W510	201.130	20/21	\$0	\$2,720	\$0	\$0	\$0	\$0	\$0	\$20	\$600	\$100	\$2,000	\$2,720
04	OOL	150		Bridge to 1.0 mile west of Observatory Peak Road.	2000	100010	201.100	20/21	ΨΟ	ΨΖ,1 ΖΟ	ΨΟ	ΨΟ	ΨΟ	ΨΟ	Ψ0	ΨΖΟ	ΨΟΟΟ	Ψ100	Ψ2,000	ΨΖ,7 ΖΟ
				Repair or replace guardrails, signs, ditches, drainage																
				and electrical facilities, remove debris and hazardous																
				trees, and install erosion control in fire damaged areas.																
04	SCL	101		In Mountain View, at North Shoreline Boulevard onramp	2804C	0W680	201.130	20/21	\$0	\$770	\$0	\$0	\$0	\$0	\$0	\$0	\$200	\$0	\$570	\$770
				to southbound Route 101. Replace culverts, inject					·											·
				polyurethane foam, and reconstruct pavement.																
04	SCL	280		In Cupertino, at Calabazas Creek Bridge No. 37-0405.	2908B	0W420	201.130	20/21	\$0	\$1,155	\$0	\$0	\$0	\$0	\$0	\$0	\$270	\$0	\$885	\$1,155
				Stabilize and lift concrete slabs by performing																
				polyurethane injection and replace damaged concrete																
				slabs.																
04	SCL	101		Near Gilroy, at Sargent Bridge and Overhead No. 39-	1453B	4J030	201.131	20/21	\$1,482	\$3,090	\$0	\$0	\$0	\$650	\$780	\$52	\$900	\$87	\$2,103	\$4,572
				0006L. Permanent restoration of roadway settlement																
0.4	001	404		and southern abutment wingwall movement.	000014	0)4/000	004.400	00/04	00	#0.070	40	00	00	40	00	400	# 550	40	#4.500	#0.070
04	SCL	101		In San Jose, at 0.2 mile north of Tully Road. Replace	2908K	2W390	201.130	20/21	\$0	\$2,070	\$0	\$0	\$0	\$0	\$0	\$20	\$550	\$0	\$1,500	\$2,070
				failed culvert, backfill eroded areas, replace irrigation																
04	SF	101		system, and install erosion control. In the City and County of San Francisco, at Central	20071/4	1W980	201.130	20/21	\$0	\$1,090	\$0	\$0	\$0	\$0	\$0	\$10	\$270	\$0	\$810	\$1,090
04	SF	101		Viaduct No. 34-0077. Replace the damaged concrete	2907 IVI	100900	201.130	20/21	φυ	φ1,090	φυ	φυ	φυ	φυ	φυ	φ10	φ270	φυ	φοισ	φ1,090
				barrier and guardrail.																
04	SM	1		Near Pescadero, from Santa Cruz County line to	2906E	1W520	201.130	20/21	\$0	\$1,080	\$0	\$0	\$0	\$0	\$0	\$20	\$260	\$50	\$750	\$1,080
•				Pescadero Creek Road. Repair or replace guardrails,				=====	,	4 1,000	**		, ,	, ,		+	4 200		4.00	V 1,000
				signs, ditches, drainage and electrical facilities, remove																
				debris and hazardous trees, and install erosion control																
				in fire damaged areas.																
04	SM	82		In South San Francisco, at 0.1 mile north of Francisco	1450J	0K670	201.131	20/21	\$1,270	\$3,806	\$0	\$0	\$0	\$500	\$710	\$60	\$800	\$27	\$2,979	\$5,076
				Drive. Permanent embankment restoration by installing																
				retaining wall and drainage improvements.																
04	SM	84		Near Woodside, at 1.1 miles south of Portola Road.		0W120	201.130	20/21	\$0	\$4,130	\$0	\$0	\$0	\$0	\$210	\$20	\$900	\$0	\$3,000	\$4,130
				Repair slipout, construct retaining wall, and install crash																
04	SM	104		cushions and guardrail. In Milipitas, at Henderson Underpass. Install new drain	30000	2///240	201.130	20/24	\$0	¢1 420	ΦO	¢0	¢0	ΦO	\$0	¢20	¢220	\$80	¢1.000	¢4 420
υ4	SIVI	101		in Milipitas, at Henderson Underpass. Install new drain pipe, erosion control, and Rock Slope Protection (RSP),	ZAUQD	2W310	ZU1.13U	20/21	φU	\$1,430	\$0	\$0	\$0	\$0	Φ0	\$30	\$320	φδυ	\$1,000	\$1,430
				and replace chainlink fence and concrete barrier.																
				ана теріасе опашши тепсе ана сопстете ватнет.																
04	SOL	37		Near Vallejo, at the Route 37/29 Separation No. 23-	2904J	0W580	201.130	20/21	\$0	\$582	\$0	\$0	\$0	\$0	\$0	\$0	\$152	\$0	\$430	\$582
				0218. Replace expansion joint system.]							, ,		,	,		
04	SOL	80		In and near Fairfield and Vacaville, from North Texas	2905E	1W490	201.130	20/21	\$0	\$3,290	\$0	\$0	\$0	\$0	\$0	\$0	\$750	\$40	\$2,500	\$3,290
				Street to Alamo Drive. Repair or replace guardrails,																
				ditches, drainage and electrical facilities, signs and																
				fencing, replace oleanders in the median, remove																
				debris and hazardous trees, and install erosion control																
				in fire damaged areas.																

July 27, 2022 2 of 6

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
	SON			Near Jenner, at 0.3 mile north of Pacific View Drive.	•	1W550		20/21	\$0	\$600	\$0	\$0	\$0	\$0	\$0	\$0	\$150	\$0	\$450	\$600
				Construct sheet pile retaining wall, stabilize slope with					Ψ.	4000	4.0	, , , , , , , , , , , , , , , , , , ,	, , , , , , , , , , , , , , , , , , ,	4.0	Ų.	ų s	4.00	4.0	Ψ.00	V
				Rock Slope Protection (RSP), replace culvert, and																
				reconstruct roadway.																
04	SON	1	27.3/31.5	Near Jenner, from 0.9 mile north of Meyers Grade Road	2906B	1W500	201.130	20/21	\$0	\$20,890	\$0	\$0	\$0	\$0	\$0	\$60	\$4,750	\$80	\$16,000	\$20,890
				to 1.5 miles south of Fort Ross Road. Repair or replace																
				guardrails, drainage systems, electrical facilities, signs																
				and fencing, repair damaged retaining walls, remove																
				debris and hazardous trees, and install erosion control																
				in fire damaged areas.																
04	SON	128	16.8/17.6	Near Healdsburg, from 0.4 mile west to 0.4 mile east of	2908E	2W330	201.130	20/21	\$0	\$2,050	\$0	\$0	\$0	\$0	\$0	\$50	\$450	\$50	\$1,500	\$2,050
				Maacama Creek Bridge. Stabilize slope, improve																
				drainage, install underdrains, remove debris and loose																
				rock, and install Rock Slope Protection (RSP) and																
04	SON	1	15 1/15 7	erosion control. Near Carmet, from 0.1 mile to 0.7 mile north of Calle	07495	0A020	201.131	20/21	\$17,698	\$40,824	\$0	\$0	\$0	\$0	\$1,800	\$500	\$5,000	\$15,398	¢25 924	\$58,522
04	SON	'	13.1/13.7	Del Sol. Realign roadway near Gleason Beach.	0746	UA020	201.131	20/21	φ17,090	φ40,024	φυ	φυ	φυ	φυ	φ1,000	φουσ	φ5,000	φ15,590	φυυ,024	φ30,322
04	SON	1	26 7/27 0	Near Jenner, from 0.3 to 0.4 mile north of Myers Grade	0482T	0.1300	201.131	20/21	\$4,810	\$19,100	\$0	\$0	\$0	\$2,106	\$2 496	\$208	\$3,137	\$243	\$15,720	\$23,910
	00.1		20.1721.0	Road. Permanent restoration of roadway slipouts.	0.02.		2011.101		ψ 1,010	φ10,100	Ψ**	Ψ**	Ψ	φ2,	ΨΞ, .σσ	Ψ200	Ψο, τοτ	Ψ2.0	φ.ο,. 20	Ψ20,010
				, commence of the contract of																
04	SON	101		Near Petaluma, north of Pepper Road. Environmental	0481G	0J101	201.131	20/21	\$0	\$140	\$0	\$0	\$0	\$0	\$0	\$0	\$140	\$0	\$0	\$140
				mitigation for project EA 0J100.																
04	ALA	880	28.3/28.5	In Oakland, under Fruitvale Avenue Overhead	2911F	4W070	201.130	21/22	\$0	\$0	\$880	\$0	\$0	\$0	\$0	\$10	\$290	\$0	\$580	\$880
				between 8th Street and 9th Street at the																
				intersection with 34th Avenue. Replace fence,																
				install double access gate, and add erosion																
				control.																
04	ALA	84		Near Fremont, at 0.5 mile south of Palomeras Road.	2912E	0Y110	201.130	21/22	\$0	\$0	\$1,450	\$0	\$0	\$0	\$0	\$50	\$420	\$20	\$960	\$1,450
				Remove debris, place erosion control, and install																
				cable net drapery system to prevent rockfall.																
04	A1 A	000	24 0/25 0	In Oakland under Deute 200 alang Wood Chroat	20445	2/4/000	204 420	24/22	60	* 0	¢4.202	60	60	60	60	600	64 200	640	¢2.002	¢4.202
04	ALA	880	34.6/35.0	In Oakland, under Route 880 along Wood Street, between West Grand Avenue and 34th Street.	2911E	3W990	201.130	21/22	\$0	\$0	\$4,363	\$0	\$0	\$0	\$0	\$20	\$1,300	\$40	\$3,003	\$4,363
				Repair fire damaged concrete column, construct																
				hardened fence, perform electrical repairs,																
				reconstruct and stabilize damaged embankment slopes, and install signs.																
04	ALA	680		In Fremont, at the northbound offramp to Mission	2028M	0Q680	201.131	21/22	\$750	\$945	\$3,946	\$0	\$0	\$750	\$885	\$60	\$1,033	\$5	\$2,908	\$5,641
0-7	, \L, \	000		Boulevard. Stabilize storm damaged embankment.	ZOZOW	00000	201.101	21/22	Ψίου	ψυπο	ψο,σ-ισ	ΨΟ	ΨΟ	Ψίου	ΨΟΟΟ	ΨΟΟ	Ψ1,000	ΨΟ	Ψ2,000	ψο,ο ι
04	ALA	92		In Hayward, at the westbound connector from	2028K	0Q450	201.131	21/22	\$285	\$363	\$862	\$0	\$0	\$285	\$347	\$16	\$191	\$10	\$661	\$1,510
				northbound Route 880. Restore eroded embankment		,			•	,	,		, -	,	• -	•		, -	•	, ,
				and extend existing concrete barrier.																
04	ALA	260	1.1/1.9	In the cities of Alameda and Oakland, at the Posey	2909B	2W740	201.131	21/22	\$0	\$0	\$8,550	\$0	\$0	\$0	\$0	\$0	\$2,050	\$0	\$6,500	\$8,550
				Tube No. 33-0106R (PM R1.1R to R1.9R) and Webster																
				Tube No. 33-0106L (PM R1.1L to R1.9L). Install fuel																
				cell power supply systems to maintain safety systems in																
				the event of a fire emergency.	0000	016:==	00115	0.1/5-		**	A C 4 C					A 15	42==	6.5	A	A. 1. =
04	CC	80		Near San Pablo, on El Portal Drive onramp to	2909P	3W770	201.130	21/22	\$0	\$0	\$815	\$0	\$0	\$0	\$0	\$10	\$270	\$10	\$525	\$815
				westbound Route 80. Reconstruct the damaged																
0.4		0.4		soundwall and concrete barrier.	20445	4\4(000	204 422	04/00	*	40	0005	**	*	40	*	640	6005	40	6050	6005
04	CC	2 4		Near Orinda, at eastbound onramp from Fish Ranch	Z911B	444330	201.130	21/22	\$0	\$0	\$965	\$0	\$0	\$0	\$0	\$10	\$305	\$0	\$650	\$965
				Road. Remove debris, reestablish slope and																
				drainage, and repair or replace the damaged																
				rockfall fence system.																

July 27, 2022 3 of 6

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
04		680		In Danville, at 0.2 mile south of El Pintado Road	2911Q			21/22	\$0	\$0	\$990	\$0	\$0	\$0	\$0	\$0	\$310	\$0	\$680	\$990
				Undercrossing. Stabilize foundation soils and					·	·	'	·		·		·	·	·		
				pavement by injecting cement grout using																
				compaction grouting techniques, line the damaged																
				culverts, and repair pavement.																
04	MRN	101	3.5/4.7	Near Sausalito, at Richardson Bay Bridge No. 27-0010.	2909E	3W390	201.130	21/22	\$0	\$0	\$935	\$0	\$0	\$0	\$0	\$0	\$325	\$0	\$610	\$935
				Remove damaged expansion joint, repair concrete																
				section, and install new finger joints.																
04	MRN	1		Near Stinson Beach, at 0.7 mile south of Panoramic	2034J	0W130	201.131	21/22	\$0	\$479	\$1,845	\$0	\$0	\$0	\$454	\$25	\$500	\$31	\$1,314	\$2,324
				Highway. Implement permit requirements including																
				plant establishment, noxious weed control, seed																
				collection and propagation, and biological monitoring for																
-				emergency project EA 0P130.	004484	414/550	004.400	04/00	20		04.050		•		**	A4=	***	A 4 =	***	A4 0=0
04	NAP	80		Near Vallejo, at 0.8 mile west of American Canyon	2911M	400/50	201.130	21/22	\$0	\$0	\$1,070	\$0	\$0	\$0	\$0	\$15	\$360	\$45	\$650	\$1,070
				Road; also in Solano County, on Route 80 at Lynch																
				Road Undercrossing No. 23-0014L (PM R9.7).																
				Reconstruct the side slopes and reestablish the damaged berm and drainage system.																
04	NAD	29	12 8/12 9	Near Calistoga, from 3.3 miles to 3.4 miles north of	2913B	07440	201.130	21/22	\$0	\$0	\$1,525	\$0	\$0	\$0	\$0	\$20	\$520	\$60	\$925	\$1,525
04	IVAI	23	72.0/72.3	Tubbs Lane. Reconstruct damaged slope, install	23135	01440	201.100	21/22	ΨΟ	ΨΟ	ψ1,020	Ψ	Ψ0	Ψ	ΨΟ	Ψ20	ΨΟΣΟ	ΨΟΟ	Ψ323	Ψ1,020
				horizontal drains, and place erosion control.																
04	NAP	29	11.6/13.0	In Napa, from First Street to 0.1 mile south of Redwood	2022G	0Q820	201.131	21/22	\$1,437	\$0	\$16,619	\$0	\$0	\$1,437	\$1,792	\$152	\$1,228	\$44	\$13,403	\$18,056
				Road/Trancas Street. Repair culvert.					. ,	·	' '	·		. ,	. ,		. ,		. ,	. ,
04	NAP	12	2.1/2.6	Near the city of Napa, from 1.2 miles to 0.7 mile west of	2021F	0Q690	201.131	21/22	\$308	\$470	\$1,779	\$0	\$0	\$308	\$320	\$150	\$400	\$134	\$1,245	\$2,557
				the Solano County line. Repair storm damaged slopes																
				at two locations with Rock Slope Protection (RSP) and																
				restore ditches.																
04	SCL	152	10.2/10.4	In Gilroy, from Route 101 to Camino Arroyo.	2910B	3W840	201.130	21/22	\$0	\$0	\$790	\$0	\$0	\$0	\$0	\$0	\$260	\$0	\$530	\$790
				Reconstruct damaged pavement, repair light pole, sign																
				posts, and landscaping, clean drainage system, and																
-	CCI	200		remove hazardous waste.	2912H	07.500	204 420	24/22	60	¢ 0	62.000	60	60	60	# 0	60	¢500	60	¢4 500	#2.000
04	SCL	280		In San Jose, at Bird Avenue Overcrossing. Repair existing and install new pumps.	2912H	01500	201.130	21/22	\$0	\$0	\$2,080	\$0	\$0	\$0	\$0	\$0	\$580	\$0	\$1,500	\$2,080
04	SCL	101		In Mountaiview, at Moffet Boulevard Overcrossing	2014D	07070	201 130	21/22	\$0	\$0	\$3.080	\$0	\$0	\$0	\$0	\$0	\$880	\$0	\$2,200	\$3.080
04	JOL	101		No. 37-0105. Repair bridge girders damaged by a	23140	01370	201.130	21/22	Ψυ	φυ	\$3,000	ΨU	φυ	φυ	φυ	Ψυ	\$000	φυ	φ2,200	φ3,000
				high-load hit.																
04	SCL	9		In Saratoga, north of Pierce Road (PM 5.97). Install	1464D	2K280	201.131	21/22	\$484	\$0	\$1,589	\$0	\$0	\$130	\$318	\$36	\$315	\$10	\$1,264	\$2,073
	002			Rock Slope Protection (RSP) and replace culvert.	1 10 15	211200	201.101	- 1/	Ψίσι	ΨΟ	Ψ1,000	ΨΟ	Ψ**	Ψίου	ΨΟΙΟ	ΨΟΟ	ΨΟΙΟ	Ψισ	Ψ1,201	Ψ2,070
04	SM	280		In Daly City, at 0.1 mile south of Route 1 Connector.	2912F	0Y410	201.130	21/22	\$0	\$0	\$1,635	\$0	\$0	\$0	\$0	\$0	\$465	\$0	\$1,170	\$1,635
				Replace culvert, backfill sinkhole, and restore																·
				landscaping.																
04	SM	1		Near Montara, at 0.2 mile north of Gray Whale Cove	2912M	0Y480	201.130	21/22	\$0	\$0	\$1,295	\$0	\$0	\$0	\$0	\$0	\$420	\$0	\$875	\$1,295
				Parking Lot. Install rock slope protection and																
				drainage system, and place erosion control.																
04	SM	84	24.5/24.8	In Redwood City, along the area between the Route	2913G	0Y610	201.130	21/22	\$0	\$0	\$1,773	\$0	\$0	\$0	\$0	\$0	\$610	\$0	\$1,163	\$1,773
1				82 (El Camino Real) and Route 84 (Woodside																
1				Road). Reconstruct damaged slopes by grading																
				and installing rock slope protection and boulder																
				rocks, install fencing, clear debris and hazardous																
				waste, and place erosion control.																
04	SM	101		In Burlingame, at Broadway offramp. Remove and	2914E	0Y950	201.130	21/22	\$0	\$0	\$1,060	\$0	\$0	\$0	\$0	\$0	\$330	\$0	\$730	\$1,060
21	C::			replace the damaged pavement.	4.45011	014576	004.404	04/00	A77 0	40	04.400	40		# 2000	# 400	A=0	# 500	40	#	# 0.000
04	SM	1		Near Half Moon Bay, at 1.1 miles north of Santa Cruz	1450H	0K570	201.131	21/22	\$770	\$0	\$1,492	\$0	\$0	\$300	\$400	\$70	\$500	\$2	\$990	\$2,262
				County line. Repair slope washout by constructing a																
				soldier pile wall and upgrading the drainage system.																

July 27, 2022 4 of 6

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
04	SM			Near La Honda, at 1.2 miles north of Madera Lane	1455B			21/22	\$936	\$400	\$4,047	\$0	\$0	\$936	\$390	\$10	\$750	\$30	\$3,267	\$5,383
04	Olvi	04		(north). Repair slope washout and place Rock Slope	14000	211010	201.101	21/22	ψυσο	Ψ+00	ψτ,υτι	ΨΟ	ΨΟ	Ψυσο	ΨΟΟΟ	Ψισ	Ψίσο	ΨΟΟ	ψ0,201	ψ0,000
				Protection (RSP) on existing embankment to prevent																
				further erosion.																
04	SON	101		Near Cloverdale, at 0.4 mile south of the Mendocino	1462P	2K350	201.131	21/22	\$840	\$541	\$3,304	\$0	\$0	\$840	\$413	\$128	\$459	\$225	\$2,620	\$4,685
				County line. Restore slope, rebuild damaged gutter and					70.0	4	40,000	, ,		, , , ,	*	¥	,	7	+ =,-=-	+ 1,555
				install erosion control measures.																
04	SON	1	15.1/15.7	Near Carmet, from 0.1 mile to 0.7 mile north of Calle	0748R	0A021	201.131	21/22	\$7,000	\$0	\$1,400	\$0	\$0	\$0	\$0	\$0	\$1,400	\$7,000	\$0	\$8,400
				Del Sol. Biological mitigation for project EA 0A020.					. ,		. ,	·	·		·	·	. ,	. ,	·	. ,
04	SON	1	15.1/15.7	Near Carmet, from 0.1 mile to 0.7 mile north of Calle	0748S	0A022	201.131	21/22	\$1,000	\$0	\$200	\$0	\$0	\$0	\$0	\$0	\$200	\$1,000	\$0	\$1,200
				Del Sol. Stormwater mitigation for project EA 0A020.																
04	ALA	580		Near Livermore, at 0.3 mile west of Stonecut	1461D	0P120	201.131	22/23	\$752	\$0	\$1,467	\$4,930	\$0	\$752	\$1,362	\$105	\$1,270	\$70	\$3,590	\$7,149
				Underpass (PM R4.3L). Restore eroded embankment																
				slope in the eastbound direction and install erosion																
				control measures.																
04	CC	680	19.2/19.9	·	2028N	0Q780	201.131	22/23	\$608	\$0	\$818	\$2,950	\$0	\$608	\$752	\$66	\$807	\$24	\$2,119	\$4,376
				Undercrossing No. 28-0178 and Concord Avenue																
				Undercrossing No. 28-0190. Stabilize storm damaged																
				abutment slopes by paving with concrete.																
04	NAP	121	16.0/16.1	Near Napa, at Wooden Valley Road. Repair pavement,	2022F	0Q810	201.131	22/23	\$0	\$902	\$1,460	\$2,060	\$0	\$902	\$1,287	\$173	\$661	\$86	\$1,313	\$4,422
0.4	014	4		replace drainage systems, and upgrade guardrail.	000011	00070	004.404	00/00	0.440	Φ0	* 4.4.5	#4.000	40	0.440	# 000	407	4070	405	# 4.400	00.044
04	SM	1		Near Montara, at south of 9th Street. Repair damaged	2028H	0Q670	201.131	22/23	\$418	\$0	\$415	\$1,808	\$0	\$418	\$388	\$27	\$373	\$35	\$1,400	\$2,641
0.4	CNA	0.4		storm drain and restore eroded embankment.	44550	01/040	004 404	00/00	Φ4 OFC	ФО 7.Г	Φ0	Φ4.0E7	Φ0	Φ4 OFC	ሰ ርጋር	0.40	#404	#074	#0.000	ФГ 700
04	SM	84		Near La Honda, west of Peek-A-Boo Lane. Construct	1455C	2K640	201.131	22/23	\$1,056	\$675	\$0	\$4,057	\$0	\$1,056	\$635	\$40	\$484	\$371	\$3,202	\$5,788
				soldier pile wall, reconstruct damaged pavement, and																
04	SM	0.4		upgrade guardrail. Near La Honda, at 0.5 mile west of Pescadero Creek	2032A	00490	201.131	22/23	\$924	\$0	\$809	\$4,762	\$0	\$924	\$809	\$33	\$522	\$146	\$4,061	\$6,495
04	SIVI	04		,		UQ46U	201.131	22/23	Φ924	ΦО	\$009	\$4,762	\$0	φ924	фола	φοο	Φ 322	\$140	\$4,001	Ф 0,495
				Road. Repair slope washout by constructing a retaining wall.																
04	SOL	505		Near Vacaville, at southbound offramp to Allendale	2021G	00710	201.131	22/23	\$317	\$0	\$500	\$1,276	\$0	\$317	\$402	\$98	\$385	\$50	\$841	\$2,093
04	OOL	303		Road. Restore slope washout between offramp and	20210	00/10	201.101	22/20	ΨΟ17	ΨΟ	Ψοσο	Ψ1,270	ΨΟ	ΨΟ17	ΨτυΖ	ΨΟΟ	ΨΟΟΟ	ΨΟΟ	ΨΟΤΙ	Ψ2,000
				adjacent frontage road by placing rock slope protection.																
				ladjudent frontage road by placing rook slope protection.																
04	SON	116		Near Monte Rio, at 0.2 mile west of Cnopius Road.	1464F	2K360	201.131	22/23	\$1,775	\$0	\$2,087	\$7,805	\$0	\$1,775	\$1.883	\$204	\$0	\$384	\$0	\$4,246
				Repair unstable slope by constructing a retaining wall.				,_	V ., C	4.0	4=,00.	4 1,000	, , , , , , , , , , , , , , , , , , ,	4 ., 6	V ., CCC	Ψ=0.	4.0	400.	4.0	¥ .,= .•
				(G13 Contingency)																
04	SON	121	9.7/10.3	Near Schellville, from 0.2 mile to 0.8 mile north of	2021D	4K140	201.131	22/23	\$528	\$972	\$0	\$4,719	\$0	\$528	\$941	\$31	\$668	\$11	\$4,040	\$6,219
				Ramal Road. Restore structural integrity of the existing														·	,	,
				roadway by injecting polyurethane to densify the soil																
				below and minimizing future settlement, grind and																
				replace asphalt concrete, and rehabilitate drainage																
				systems.																
04	NAP	121	13.4/20.7	Near Napa, from 2.8 miles north of Vichy Avenue to 1.4	2022D	0Q790	201.131	23/24	\$0	\$1,635	\$0	\$2,252	\$6,304	\$1,635	\$2,053	\$199	\$1,361	\$639	\$4,304	\$10,191
				miles south of Route 128 at various locations. Repair																
				and restore slope washouts with Rock Slope Protection																
				(RSP), erosion control, steel sheet piles, and drainage																
				upgrades.																
04	NAP	29		Near Calistoga, at 2.5 miles south of Lake County line.	2022H	0Q830	201.131	23/24	\$0	\$736	\$1,003	\$0	\$2,323	\$736	\$885	\$118	\$878	\$165	\$1,280	\$4,062
	0.0:	150	00 = 100 =	Stabilize storm damaged embankment.	000 (11)	000==	004 101	00/5/		A=		0.55	40.5:-	4555	* 4 5 5	400	45	* 4 5 5	A.	40.100
04	SCL	152	20.5/20.8	Near Gilroy, from 0.8 mile east to 1.1 miles east of San		3Q650	201.131	23/24	\$0	\$583	\$0	\$581	\$2,245	\$583	\$492	\$89	\$556	\$168	\$1,521	\$3,409
				Felipe Road. Stabilize slope with Rock Slope Protection																
				(RSP), erosion control, and drainage upgrades.																
0.4	0011	440		New James et 4.4 miles end of Double 4. Double	20240	04400	004.404	00/04	Φ0	Φ4 400	Φ0	ф 7 00	04.440	#4.400	Φ 7 4Ω	Φ 7 0	Ф740	# 050	ΦO 750	ФС 000
04	SON	176		Near Jenner, at 1.1 miles east of Route 1. Permanent	2031S	UAA63	201.131	23/24	\$0	\$1,130	\$0	\$780	\$4,119	\$1,130	\$710	\$70	\$710	\$656	\$2,753	\$6,029
				restoration of slope by reconstructing culvert wingwalls																
				and placing Rock Slope Protection (RSP).																

July 27, 2022 5 of 6

FOR 2019/2024 PROGRAM YEARS
All amounts in \$1,000

Dist	Co	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	20/21	21/22	22/23	23/24	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
04	SON	1	26.7/27.1	Near Jenner, from 0.3 to 0.7 mile north of Myers Grade	2911P	0J301	201.131	23/24	\$0	\$0	\$0	\$1,010	\$5,972	\$0	\$1,000	\$10	\$2,800	\$0	\$3,172	\$6,982
				Road. Mitigation project for EA 0J300 for plant																
				establishment and erosion control.																
04	MRN	1		Near Muir Beach, at 0.6 mile south of Pacific Way.	2906H	3AA50	201.131	25/26	\$1,054	\$0	\$0	\$0	\$1,934	\$1,054	\$1,729	\$205	\$0	\$0	\$0	\$2,988
				Repair and extend retaining wall, replace culvert and																
				guardrail, and repair pavement.																
04	MRN	101	6.1/6.3	In Corte Madera, from 0.4 mile to 0.6 mile north of		2AA30	201.131	25/26	\$714	\$0	\$0	\$0	\$993	\$714	\$964	\$29	\$0	\$0	\$0	\$1,707
				Route 131 (Tiburon Boulevard). Restore slope, regrade																
				unlined ditch, and install erosion control measures.																
04	MRN	131	1.9/2.0	In Tiburon, east of Trestle Glen Boulevard.	2906J	3AA90	201.131	25/26	\$962	\$0	\$1,459	\$0	\$3,504	\$962	\$1,227	\$232	\$630	\$298	\$2,576	\$5,925
				Stabilize roadway by constructing a retaining wall.																
04	NAP	128		Near Saint Helena, at 1.2 miles east of Chiles Pope	2906G	4AA30	201.131	25/26	\$1,539	\$0	\$0	\$0	\$0	\$1,539	\$0	\$0	\$0	\$0	\$0	\$1,539
				Valley Road. Construct retaining wall, rehabilitate																
				drainage system, and install erosion control to stabilize																
				slope.																
	2020 SHOPP - Emergency Response TOT										\$80,357	\$38,990	\$27,394	\$23,875	\$29,461	\$3,968	\$60,476	\$28,330	\$210,525	\$356,635
	SHOPP - Emergency Response NEW REQUESTED TO									\$166,834	\$80,357	\$38,990	\$27,394	\$25,102	\$30,961	\$4,146	\$61,716	\$28,511	\$212,527	\$362,963
	SHOPP - ER PROGRAMMED TO									\$166,834	\$56,732	\$38,990	\$23,890	\$24,140	\$29,734	\$3,789	\$54,296	\$28,048	\$194,865	\$334,872
	SHOPP - ER DIFFERENCE TOT									\$0	\$23,625	\$0	\$3,504	\$962	\$1,227	\$357	\$7,420	\$463	\$17,662	\$28,091

July 27, 2022 6 of 6